ABSTRACT

An inspection method can easily determine welding condition by just comparing an echo height returned from the weld zone of a real product with a master data.

An master data is made based on the data from prepared test pieces corresponding to the real product.